



Dominion

DAM INSPECTION CHECKLIST POSSUM POINT POWER STATION POND ABC

INSPECTION DATE: 11/20/15 1153 hrs

WEATHER: Partly cloudy, 37°F

INSPECTED BY: D. West, J. Marcell, M. Winters

Location/ Condition	(y/n)	Change (y/n)	Comments
Low Point, A dike*			
Flow	N	N	1153 hrs. Small amount of standing water behind sandbagged area. Sand bags and rip rap in place.
Erosion	N	N	Road wet from rain.
Low Point, B dike*			
Flow	N	N	1155 hrs. No standing water. Sand bags and rip rap
Erosion	N	N	in place. A couple minor tears in sandbags.
Outfall			
water surface El. (top of stoplogs to water)			1203 hrs. 64". No discharge. A few drops of water seeping into concrete weir structure at a rate of roughly 2 drips every 2 seconds.

* See figure below.

No standing water.

Additional Comments (Note any changes observed along the embankment crest or downstream slope observed from the crest.): Water in road ruts near "A" and "C".
0.42 inches of rain on 11/19/15.

High Tide 1840 hrs Low Tide 0113

